

Badbar Construction Camp, Sangrur

1. Black smoke was observed from bitumen heating tank and its monitoring need to be submitted.
2. As suggested earlier inspection, spillage of bitumen is still observed on soil and no preventive measures were taken up.
3. It is observed that bituminous mix falling from the conveyor belt. It was suggested to place GI sheet under the conveyor belt and prevent wastage.
4. The source of earth used for berm preparation need to be submitted, as it is observed that source as specified in site plan submitted is not being used.
5. The kitchen which was to be non functional, is found to be in use.
6. The rate of progress for toilet construction is slow and needs to be expedited, to make it functional at earliest.
7. Brick platform with soil soling is being provided all on two side of the bitumen storage tank.
8. Brick platform for storage of waste bitumen drum is prepared, but of smaller area. This needs to be of larger area.
9. The spillage from the oil storage tank is still observed and no preventative measures have been taken.
10. The fire safety measures as suggested during earlier inspection is not being fully complied, only bucket with sand is being provided and fire extinguisher is absent in all locations to be provided.
11. The parking management of transportation vehicle is managed properly.
12. The sludge collection platform was being used effectively, but disposal mechanism is not as per PPCB guideline listed in NOC.

Additional Observation

1. Crack was observed at two locations (km 1.900 and km 1.700).
2. Patch works on freshly laid bitumen carpet was also visible.